

First Street	Distance R	Second street I or landmark	Crash Number	Date	Day	Time	Description of Events	Crash Factors	Road	Natural Light	Weather	Junction	Cntrl	Tot Inj F S M A E I T R N
35/308/9.837	1450N SIRRAH ST		2853202	17/06/2008	Tue	0455	VAN1 NBD on SH 35 lost control; went off road to left, VAN1 hit Cliff Bank	(ENV = Environmental factors) VAN1 lost control due to road conditions, did not see or look for other party until too late. ENV: road obstructed (flood waters), heavy rain	Wet	Dark	Heavy Rain	Unknown	Nil	
35/308/10.287	1000E SIRRAH ST		2713657	25/11/2007	Sun	0004	CAR1 SBD on SH 35 lost control turning right on right hand bend	CAR1 lost control when turning	Dry	Dark	Fine	Unknown	Nil	1
35/308/10.387	900N SIRRAH ST		201050544	30/01/2010	Sat	0515	CAR1 SBD on SH 35 lost control turning right, CAR1 hit Cliff Bank on right hand bend	CAR1 alcohol suspected, failed to notice bend in road	Wet	Dark	Heavy Rain	Unknown	Nil	
35/308/10.447	840N SIRRAH ST		201012387	13/07/2010	Tue	1545	CAR1 NBD on SH 35 lost control turning right, CAR1 hit Cliff Bank on right hand bend	CAR1 lost control when turning, attention diverted by other traffic	Dry	Overcast	Fine	Unknown	Nil	1
35/308/10.458	2500S MAKORORI BEACH ROAD		2613388	06/12/2006	Wed	0730	CAR1 SBD on SH 35 lost control turning right on right hand bend	CAR1 too fast entering corner	Wet	Overcast	Light Rain	Unknown	Nil	1
35/308/10.787	500N SIRRAH ST		2911461	27/02/2009	Fri	0850	CAR1 NBD on SH 35 cutting corner hit CAR2 head on	CAR1 on incorrect side of the island or median, overseas/migrant driver failed to adjust to NZ road rules and road conditions. ENV: road surface under construction or maintenance	Dry	Bright	Fine	Unknown	Nil	1 2